

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MD,  
13-BELA,  
3A-

Liriodendron  
502 West Gordon Street  
Bel Air  
Harford County  
Maryland

HABS No. MD-327

Documentation: 11 sheets (1980, including site plan; plan and elevation of  
corn crib; and plans, elevations, sections and  
construction details of barn)

34 exterior photos (1980)

17 interior photos (1980)

1 set of field records (11 notebooks, 135 photos)

Walter Smalling, Jr., Photographer      January, 1980

Barn and Carriage House

- MD-327 A-1    GENERAL VIEW LOOKING NORTH
- MD-327 A-2    SOUTHWEST AND SOUTHEAST SIDES
- MD-327 A-3    SOUTHWEST AND SOUTHEAST SIDES FROM FARTHER EAST
- MD-327 A-4    SOUTHEAST SIDE
- MD-327 A-5    SOUTHEAST AND NORTHEAST SIDES
- MD-327 A-6    NORTHEAST AND NORTHWEST SIDES
- MD-327 A-7    NORTHWEST SIDE, DOOR CLOSED
- MD-327 A-8    NORTHWEST SIDE, DOOR OPEN
- MD-327 A-9    NORTHWEST AND SOUTHWEST SIDES, DOOR CLOSED
- MD-327 A-10    NORTHWEST AND SOUTHWEST SIDES, DOOR OPEN
- MD-327 A-11    NORTHWEST AND SOUTHWEST SIDES FROM FARTHER WEST
- MD-327 A-12    SOUTHWEST SIDE
- MD-327 A-13    DETAIL OF SOUTHEAST SIDE OF BARN
- MD-327 A-14    DETAIL OF LOWER LEVEL OF SOUTHEAST SIDE OF BARN
- MD-327 A-15    DETAIL OF CLOSED DOOR, SOUTHEAST SIDE OF BARN
- MD-327 A-16    DETAIL OF OPEN DOOR, SOUTHEAST SIDE OF BARN
- MD-327 A-17    DETAIL OF SOUTHEAST SIDE OF CARRIAGE HOUSE

MD-327 A-18 DETAIL OF NORTH CORNER OF CARRIAGE HOUSE  
MD-327 A-19 DETAIL OF EYEBROW DORMERS, NORTHWEST SIDE OF CARRIAGE HOUSE  
MD-327 A-20 DETAIL OF NORTH JUNCTURE OF BARN AND CARRIAGE HOUSE, LOOKING SOUTH  
MD-327 A-21 DETAIL OF NORTH JUNCTURE OF BARN AND CARRIAGE HOUSE, LOOKING EAST  
MD-327 A-22 BARN INTERIOR, LOOKING SOUTHWEST  
MD-327 A-23 BARN INTERIOR, SOUTHWEST WALL  
MD-327 A-24 BARN INTERIOR, NORTHEAST WALL  
MD-327 A-25 BARN INTERIOR, UPPER FLOOR, LOOKING NORTHWEST  
MD-327 A-26 BARN INTERIOR, UPPER FLOOR, LOOKING SOUTHEAST  
MD-327 A-27 BARN INTERIOR, UPPER FLOOR, LOOKING NORTHEAST  
MD-327 A-28 BARN INTERIOR, LOOKING SOUTHEAST FROM UPPER FLOOR TO MIDDLE FLOOR  
MD-327 A-29 BARN INTERIOR, LOOKING SOUTH FROM UPPER FLOOR TO MIDDLE FLOOR  
MD-327 A-30 BARN INTERIOR, DETAIL OF CEILING  
MD-327 A-31 BARN INTERIOR, DETAIL OF COLUMN, BEAM, BRACING  
MD-327 A-32 CARRIAGE HOUSE INTERIOR, UPPER FLOOR, LOOKING NORTH  
MD-327 A-33 CARRIAGE HOUSE INTERIOR, UPPER FLOOR, LOOKING NORTHEAST  
MD-327 A-34 CARRIAGE HOUSE INTERIOR, UPPER FLOOR, LOOKING SOUTHWEST  
MD-327 A-35 CARRIAGE HOUSE INTERIOR, MIDDLE FLOOR, LOOKING SOUTH  
MD-327 A-36 CARRIAGE HOUSE INTERIOR, MIDDLE FLOOR, LOOKING NORTH  
MD-327 A-37 CARRIAGE HOUSE INTERIOR, LOWER FLOOR, LOOKING EAST  
MD-327 A-38 CARRIAGE HOUSE INTERIOR, LOWER FLOOR, LOOKING NORTHEAST